



Revised Estimate 2020-21

Appendix- "A"

Name of the Department: Food & Civil Supplies

(Rs. in lakh)

Sl. No.	Head of Development/ Account	Revised Estimate 2020-21
1	2	3
I	Normal Development Activities	
1	Repair/maintenance of Ty-III Qtr No.25 officer's Qtr at Nlg	3.50
2	C/o Drain around DRC office complex at Tezpur	2.00
3	Complete repair/renovation/maintenance, C/o Septic tank, water reservoir, overhead tank, approach road, drain and entire new wiring in the Department Qtr No.Ty-IV at Naharlagun	2.19
4	C/o RCC Ty-IV-1 No. & Ty-III Qtr 1 No along with brick boundary wall at Palin in Kra Daadi district (Jamin)	5.00
5	C/o multistoried RCC structure for utilizing as officers/ staffs Qtr in the Capital Complex (Ty-V-1 No., Ty-IV-1 No. & Ty-III-2 Nos. including C/o RCC water reservoir/ overhead tank, brick boundary wall, RCC retaining wall, drilling of bore well, drain approach road etc) at Naharlagun	5.00
6	C/o boundary & protection wall for 200 MT PDS storage godown at Bomdila	5.00
7	C/o Septic tank & soak pit for Govt.Qtr No. DCS/BB/1 & 2 at Nlg	3.00
8	Repair/renovation/maintenance of godown No.1 under Dy. Director of F&CS Rowriah (Jorhat), Assam	5.00
9	Repair/renovation/maintenance of 100 MT PDS storage old godown at Palin, Kra-Daadi district	11.00
10	C/o Directorate office building at Naharlagun (SH: C/o RCC retaining wall, earth cutting, earth filling and RCC building at premis of Directorate of Food & Civil Supplies, Naharlagun	12.00
11	Developmental works of Govt. Qtr No. DCS/Ty-I/11 [SH:Extension of 2(two) rooms & renovation of Govt. Qtr No.DCS/Ty-I/11] at Naharlagun	1.45
12	Fitting of false ceiling with lighting, fitting of window flex in the DFCS Conference Hall, Det HQ, Nlg	4.00
13	C/o office canteen, chowkider's Qtr in the DFCSO office, Yupia	2.50
14	Renovation of PDS godown at Old Ziro, Lower Subansiri district	10.00
15	Complete repair/maintenance, interior & exterior painting with weather coat & plastic distemper and fitting of window glass panel of Directorate of F&CS HQ, Naharlagun	10.00
16	Repair/maintenance of DFCSO office building at Boleng	5.00
17	Repair/maintenance of Govt. Qtr No.Ty-II/21 at Polo Colony, Naharlagun	3.00
18	Repair/ renovation of staff Qtr Ty-II-22 at Polo Colony, Naharlagun	5.00
19	Repair/renovation of BB No.4 at Polo Colony, Nlg	2.00
20	C/o Semi RCC uilding for generator shed at Bunglow No.04 at Niti Vihar, Itanagar	2.32
21	Repair/ renovation of BB No.16 staff Qtr at Polo Colony, Naharlagun	2.00
22	Additional works for Arunachal Bhawan Mohanbari against the following component which were not covered under the original estimate approved earlier	
	1. C/o G+2 RCC Ty-II Qtr (6 unit) along with brick boundary wall at Jt. Director (F&CS) cum Addl. Resident Commissioner office complex, Mohanbari	40.00
	i) T-II-6 Nos (P/A=333.48 SQM)	
	ii) Compound Wall-254.50 mtr	
	iii) Internal Road-187.00 mtr	
	iv) Steel Gate= 1 No.	
	v) Approach Road=150.00 mtr	
	Total (I)	140.96
II	State Share towards CSSs	
1	End to End Computerization of TDPS Operation under "Strengthening of PDS operation Scheme"	39.51
	Total (II)	39.51
	Grand Total (I+II)	180.47